Scanned by CamScanner

CIVIL QUALITY CONSULTANTS & ENGINEERS

(Buildings Geo-Tech & Highway Materials Testing Laboratory)
An ISO 9001: 2008 Certified Company

JAS-ANZ
ISO 9001:2000 CERTIFIED

Name of Work : Development and other works at Sidharthanagara in Ward No.16, BBMP, Bangalore.

Name of Client	:	**Executive Engineer,** Rajarajeshwari Nagara Division, BBMP, Bangalore.
Contractor/Agency	:	**M/s Sathya Borewell Cleaning, Rukmini Nagar,** Bangalore.
Total Cost	:	Rs.63.00 Lakhs
Date of Inspection	:	25.01.2018
Status of Bill	:	1st & Final Bill
In the Presence of	:	(a) **Assistant Engineer, (Rajarajeshwari Nagar Ward No.16),** BBMP, Bangalore.
	:	(b) **Mr. Mohan.G,** Sr.Engineer M/s. Civil Quality Consultants & Engineers, Bangalore.

PMC Compliance Report

Sl.No	Description of the Item		Comments / observations
1	Earthwork in surface excavation in hard soil for levelling and lowering the ground.....		Work done up to the billed quantity and Quality is satisfactory
2	Eartwork excavation for foundation of buildings, water supply, sanitary lines and electrical conduits.....		Work done up to the billed quantity and Quality is satisfactory
3	Cutting of road surface for pipeline trenches and disposing of the excavated stuff.....		Work done up to the billed quantity and Quality is satisfactory
4	Providing and fixing chorinated poly venyl chloride (CPVC) pipes conforming to IS 15778 having thermal stability.....		Work done up to the billed quantity and Quality is satisfactory
5	Providing and fixing chorinated poly venyl chloride (CPVC) pipes conforming to IS 15778 having thermal stability.....	:	Work done up to the billed quantity and Quality is satisfactory

CIVIL QUALITY CONSULTANTS & ENGINEERS Bangalore

Office : # 39, 5TH Cross, Javaregowdana Doddi, Rajarajeshwarinagar, Bangalore-560098
Laboratory : # 133, Bhuvaneshwarinagar, Dodda Basti Main Road, Bangalore - 560 056.
e-mail:civilqualityconsultants@gmail.com Ph: 8553518550/9886998316

6	Providing and fixing chorinated poly venyl chloride (CPVC) pipes conforming to IS 15778 having thermal stability.....	:	Work done up to the billed quantity and Quality is satisfactory
7	Providing and fixing chorinated poly venyl chloride (CPVC) pipes conforming to IS 15778 having thermal stability.....	:	Work done up to the billed quantity and Quality is satisfactory
8	Providing and constructing burnt brick masonry with approved quality of modular bricks.....	:	Work done up to the billed quantity and Quality is satisfactory
9	Providing and fixing in position Bib cock of approved quality 25mm nominal bore.....	:	Work done up to the billed quantity and Quality is satisfactory
10	Providing and filling sand in foundation upto plinth to required depth.....	:	Work done up to the billed quantity and Quality is satisfactory

CIVIL QUALITY CONSULTANTS & ENGINEERS Bangalore

Authorised Signatory
For CIVIL QUALITY CONSULTANTS & ENGINEERS

Authorised Signatory

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಯಶವಂತಪುರ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

Scanned by CamScanner